

Presentation Mode

Enable



Disable

Presentation Mode - Field of View

Small



Medium

Full



LOW LIGHT ILLUMINATION - MOTION DETECTION

Use the settings codes below to enable or disable low light illumination for the motion detection function of the scanner.

Enable



Disable